


# TOYOTA

Vehicle	Code	Engine Type	Year	ECU Location	Type Select SW	CarSelSW
Starlet	EPB2/M/T	4E-FTE	'89.12~'95.12	d	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	0
Starlet	EPB2/A/T	4E-FTE	'89.12~'92.1	e	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	0

\* The No.1 dip-switch on the left side is to limit timing adjustments




Signal Harness

# MITSUBISHI

Vehicle	Code	Engine Type	Year	ECU Location	Type Select SW	CarSelSW
Lancer EVO I · II	CE9A	4G63	'93.10~'95.10	b	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	C
Lancer EVO I	CD9A	4G63	'92.10~'93.10	b	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	C
GTO	Z16A	6G72	'90.10~	b	<input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>	E

\* The No.1 dip-switch on the left side is to limit timing adjustments



Signal Harness